

The conditions of software for Windows 7 and Mac OS X 10.6 (Snow Leopard) as of Sep 14, 2009

2009/09/18

| [Windows 7™](#) | [Mac OS X 10.6 \(Snow Leopard\)](#) |**■ The conditions of software for Windows 7™ are as follows:**

*The following operating conditions are the results obtained by internal tests. Note that other problems may be occurred.

*The software other than those below does not support Windows 7.

*The operation in XP mode has not been checked.

Test environment:

32-bit: Windows 7 Ultimate(x86) RTM

64-bit: Windows 7 Ultimate(x64) RTM

⊙ → Functions normally.

○ → Operable, but partially has problems.

× → Cannot be used.

Product name	Ver	Operation		Status	Measures	When settled
		32-bit	64-bit			
FineCut7 for Illustrator	7.6.2	×	×	Mimaki USB driver cannot be installed. * For the operation of Adobe Illustrator, please contact Adobe Systems Incorporated.	Mimaki USB driver for Windows 7 will be offered from December 2009 on our Website.	Dec 2009
FineCut7 for CorelDRAW	7.6.2	×	×	Mimaki USB driver cannot be installed. * For the operation of CorelDRAW, please contact Corel Corporation.	Mimaki USB driver for Windows 7 will be offered from December 2009 on our Website.	Dec 2009
SimpleCut	1.3	×	×	Mimaki USB driver cannot be installed.	Mimaki USB driver for Windows 7 will be offered from December 2009 on our Website.	Dec 2009
RasterLinkPro5 series	1.03	×	×	[1] Mimaki USB driver or IEEE1394 driver cannot be installed. [2] It does not operate even when installed on 64-bit OS. [3] ProfileManager screen is slightly defective.	[1] Mimaki USB driver and IEEE1394 driver for Windows 7 will be offered from December 2009 on our Website. [2] It will be modified on next version of RasterLinkPro5 (Dec 2009). [3] It will be modified on next version of RasterLinkPro5 (Dec 2009).	Dec 2009
Mimaki ProfileMasterII	1.22	×	×	[1] Mimaki USB driver or IEEE1394 driver cannot be installed. [2] To use a colorimeter on 64-bit OS, install the device driver separately.	[1] Mimaki USB driver and IEEE1394 driver for Windows 7 will be offered from December 2009 on our Website. [2] Download the 64-bit device driver of the colorimeter from the download site of Company x-rite.	Dec 2009
SimpleStudio	2.10	×	×	[1] It cannot be installed by the installer. [2] Mimaki USB driver cannot be installed.	[1] It will be modified on next version of SimpleStudio (Dec 2009). [2] Mimaki USB driver for Windows 7 will be offered from December 2009 on our Website.	Dec 2009
RasterLinkPro4 series	1.24	×	×	[1] Mimaki USB driver and IEEE1394 driver cannot be installed. [2] It does not operate even when installed on 64-bit OS. [3] ProfileManager screen is slightly defective.	[1] Mimaki USB driver and IEEE1394 driver for Windows 7 will be offered from December 2009 on our Website. [2] Use on 32-bit OS. [3] When starting ProfileManager, the header of the profile list screen displays defective. By changing the header size, the screen redispays	No plan

					normally.	
RasterLink3 series	1.22	×	×	<p>[1] Mimaki USB driver or IEEE1394 driver cannot be installed.</p> <p>[2] It does not operate even when installed on 64-bit OS.</p> <p>[3] ProfileManager screen display is slightly defective.</p>	<p>[1] Mimaki USB driver and IEEE1394 driver for Windows 7 will be offered from December 2009 on our Website.</p> <p>[2] Use on 32-bit OS.</p> <p>[3] When starting ProfileManager, the header of the profile list screen displays defectively. By changing the header size, the screen redispays normally.</p>	No plan
When using Windows 7 for RasterLinkPro5 client	1.03	⊙	×	<p>[Network printer sharing]</p> <p>[1] Data can be output using the printer driver from 32-bit Windows 7.</p> <p>[2] It cannot be connected from 64-bit Windows 7.</p> <p>[Hot folder sharing]</p> <p>[1] Data can be output using the hot folder.</p>	<p>[Network printer sharing]</p> <p>[2] It will be modified on next version of RasterLinkPro5 (Dec 2009).</p>	Dec 2009
When using Windows 7 for RasterLinkPro4 client	1.24	⊙	×	<p>[Network printer sharing]</p> <p>[1] Data can be output using the printer driver from 32-bit Windows 7.</p> <p>[2] It cannot be connected from 64-bit Windows 7.</p> <p>[Hot folder sharing]</p> <p>[1] Data can be output using the hot folder.</p>	From 64-bit Windows client, output using the hot folder.	No plan
When using Windows 7 for RasterLink3 client	1.22	○	×	<p>[Network printer sharing]</p> <p>[1] Data can be output using the printer driver from 32-bit Windows 7 to RasterLink3 installed on Windows Vista or XP. It cannot be connected to Windows2000.</p> <p>[2] It cannot be connected from 64-bit Windows 7.</p> <p>[Hot folder sharing]</p> <p>[1] Data can be output using the hot folder to RasterLink3 installed on Windows Vista or XP. It cannot be connected to Windows2000.</p>	From 64-bit Windows client, output using the hot folder.	No plan
When using Windows 7 for RasterLinkPro2 client	3.5	○	×	<p>[Network printer sharing]</p> <p>[1] Data can be output using the printer driver from 32-bit Windows 7 to RasterLinkPro2 installed on Windows XP. It cannot be connected to Windows2000.</p> <p>[2] It cannot be connected from 64-bit Windows 7.</p> <p>[Hot folder sharing]</p> <p>[1] Data can be output using the hot folder to RasterLinkPro2 installed on Windows XP. It cannot be connected to Windows2000.</p>	From 64-bit Windows client, output using the hot folder.	No plan
When using Windows 7 for RasterLinkPro client	5.5	×	×	<p>[Web screen display]</p> <p>[1] MicrosoftVM cannot be used.</p> <p>[2] JRE1.4 cannot be used. Though the screen displays on IE8 with JRE6 installed, RasterLinkPro does not support IE8 and JRE6 formally.</p> <p>[Network printer sharing]</p> <p>[1] Job cannot be spooled normally.</p> <p>[2] AdobePS cannot be installed.</p> <p>[Hot folder sharing]</p> <p>[1] Data can be output using the hot folder to RasterLinkPro installed on</p>	From Windows 7 client, output using the hot folder.	No plan

				WindowsXP. It cannot be connected to Windows2000. [Mistral TCP/IP Port] [2] It cannot be used.		
When using Windows 7 for RasterLinkGP client	2.3	×	×	[Network printer sharing] [1] Job cannot be spooled normally. [2] AdobePS cannot be installed. [Hot folder sharing] [1] Data can be output using the hot folder to RasterLinkGP installed on Windows XP. It cannot be connected to Windows2000.	From Windows 7 client, output using the hot folder.	No plan
When using Windows 7 for RasterLinkUJ client	2.01	×	×	[Network printer sharing] [1] Job cannot be spooled normally. [2] AdobePS cannot be installed. [Hot folder sharing] [1] Data can be output with the hot folder to RasterLinkUJ installed on Windows XP. It cannot be connected to Windows2000.	From Windows 7 client, output using the hot folder.	No plan
USB1.1 Driver	1.20	×	×	It cannot be installed.	Mimaki USB 1.1 driver for Windows 7 will be offered from December 2009 on our Website.	Dec 2009
USB2.0 Driver	1.10	×	×	It cannot be installed.	Mimaki USB 2.0 driver for Windows 7 will be offered from December 2009 on our Website.	Dec 2009
IEEE1394 Driver	2.20	×	×	It cannot be installed.	Mimaki IEEE1394 driver for Windows 7 will be offered from December 2009 on our Website.	Dec 2009

■ **The conditions of software for Mac OS X 10.6 (Snow Leopard) are as follows:**

*The following operating conditions are the results obtained by internal tests. Note that other problems may be occurred.

Test environment:

Mac OS X 10.6 Build 10A432

◎ → Functions normally.

○ → Operable, but partially has problems.

×

Product name	Ver	Operation	Status	Measures	When settled
FineCut7 for Illustrator	7.6.3	◎	It operates normally. * For the operation of Adobe Illustrator, please contact Adobe Systems Incorporated.		Completed
When using OS10.6 for RasterLinkPro5 client	1.03	○	· SMB connection Data can be output using the printer driver or the hot folder. · AppleTalk connection It cannot be connected.	Even if using PC MACLAN, it cannot be connected with AppleTalk. Connect with SMB.	No plan
When using OS10.6 for RasterLinkPro4 client	1.24	○	· SMB connection Data can be output using the printer driver or the hot folder. · AppleTalk connection It cannot be connected.	Even if using PC MACLAN, it cannot be connected with AppleTalk. Connect with SMB.	No plan

When using OS10.6 for RasterLink3 client	1.22	○	<p>[Network printer sharing] · SMB connection Data can be output using the printer driver to RasterLink3 installed on Windows Vista or XP. It cannot be connected to Windows2000.</p> <p>· AppleTalk connection It cannot be connected.</p> <p>[Hot folder sharing] · SMB connection Data can be output using the hot folder to RasterLink3 installed on Windows Vista or XP. It cannot be connected to Windows2000.</p> <p>· AppleTalk connection It cannot be connected.</p>	Even if using PC MACLAN, it cannot be connected with AppleTalk. Connect with SMB.	No plan
When using OS10.6 for RasterLinkPro2 client	3.5	×	<p>[Network printer sharing] It cannot be connected.</p> <p>[Hot folder sharing] It cannot be connected.</p>	<ul style="list-style-type: none"> · Even if using PC MACLAN, it cannot be connected. · Please consider the purchase of RasterLinkPro5 series. 	No plan
When using OS10.6 for RasterLinkPro client	5.5	×	<p>[Web screen display] Though the screen can be displayed on Safari, some problems may occur, such as missing of the part of the screen, or disabling of the cursor key. RasterLinkPro supports only Internet Explorer as a browser formally.</p> <p>[Network printer sharing] It cannot be connected.</p> <p>[Hot folder sharing] It cannot be connected.</p>	<ul style="list-style-type: none"> · Even if using PC MACLAN, it cannot be connected. · Please consider the purchase of RasterLinkPro5SG. 	No plan
When using OS10.6 for RasterLinkGP client	2.3	×	<p>[Network printer sharing] It cannot be connected.</p> <p>[Hot folder sharing] It cannot be connected.</p>	<ul style="list-style-type: none"> · Even if using PC MACLAN, it cannot be connected. · Please consider the purchase of RasterLinkPro5TA. 	No plan
When using OS10.6 for RasterLinkUJ client	2.01	×	<p>[Network printer sharing] It cannot be connected.</p> <p>[Hot folder sharing] It cannot be connected.</p>	<ul style="list-style-type: none"> · Even if using PC MACLAN, it cannot be connected. · Please consider the purchase of RasterLinkPro5IP. 	No plan

 Close